
Temperature sensor PT100







Technical data

Width:	9 mm
Depth:	42 mm
Height:	6 mm

Similar to illustration, technical modifications reserved. Without decoration.

The PT100 temperature sensor is used for the precise monitoring and documentation of temperatures during the storage and transport of temperature-sensitive products. The PT100 temperature sensor enables reliable sorting and organisation of goods to ensure quality throughout the entire logistics process.

Time and date of the request:All information / dimensions are approximate, technical changes reserved. © Hupfer19.04.2025, 13:44:03